

---

# Rustic Wood Star Sconce

---



---

## Supplies

1×3 about 4"  
1×4 about 24"  
1×5 about 12"  
1-1/4" wood screws  
votive holder  
flameless candle  
twine  
Rust-Oleum Ultimate Wood Stain Dark Walnut

---

## Tools

Miter saw  
Jig saw  
DEWALT Drill  
staple gun  
1-7/8" Forstner bit  
Countersink drill bit


**Step 1. Trace and Cut the Star.** Trace the star on a piece of 11-1/2" x 11-1/2" wood. I used two pieces of 1x4 and one piece of 1x5 cut to 11-1/2" and glued together. You could also use a piece of 3/4" plywood or any combination of 1x wood to form a piece 11-1/2" x 11-1/2".




Trace a star on the wood. I used the star I had, but you can also find a clipart star on the web. Once the star was traced, I cut the star with my bandsaw. You can also use a jig saw to cut the star.



**Step 2. Make the Holder.** Cut a piece of 1x3 to 3-3/4". Locate the center of the holder by placing a straightedge diagonally.



Use 1-7/8" forstner bit to drill a slight hole in the holder.



This hole will keep the votive holder in place.



**Step 3.** Attach the Holder. Place the holder on the star, so it's level and trace around the holder.



Drill two holes in the front, just until the drill bit protrudes from the back.



Then using the two holes on the back, drill two countersink holes.



Clamp the holder to the star and drill into the holder.



Attach the holder using 1-1/4" wood screws.



**Step 4.** Sand and Stain. Sand the star and holder. Apply a coat of dark walnut stain.



**Step 5. Attach Hanger.** Cut a piece of twine and attach to back using a staple gun.

